

PARTS LIST MODEL 0-2 -- HEATHKIT OSCILLOSCOPE

RESISTORS

R1 & R2	1 meg potentiometers	R17	100,000 $\frac{1}{2}$ watt resistors
R3 & R4	1000 ohm $\frac{1}{2}$ watt resistors	R18	100,000 ohm potentiometer
R6	10,000 ohm $\frac{1}{2}$ watt resistors	R21	470 ohm $\frac{1}{2}$ watt resistor
R7 & R8	3.2 megohm $\frac{1}{2}$ watt res.	R22	100,000 ohm potentiometer
R9 & R10	1 meg potentiometers	R23	10,000 ohm $\frac{1}{2}$ watt resistor
R11 & R12	100,000 ohm $\frac{1}{2}$ watt res.	R24	100,000 ohm 2 watt resistor
R13	150,000 ohm 2 watt res.	R25	1200-1500 ohm $\frac{1}{2}$ watt resistor
R14	1 megohm $\frac{1}{2}$ watt res.	R26	500,000 ohm $\frac{1}{2}$ watt resistor
R15	500,000 ohm $\frac{1}{2}$ watt res.	R27	7 megohm potentiometer
R16	250,000 ohm potentiometer	R19	1 megohm $\frac{1}{2}$ watt resistor

CONDENSERS

C1 & C2	.5 MFD bathtub condensers	C12	.5 MFD bathtub condenser
C3 & C4	.005 MFD condensers	C13	.1 MFD tubular condenser
C5	2. MFD bathtub condenser	C14	.02 MFD tubular condenser
C6 & C7	.1 MFD bathtub condenser	C15	.003 MFD tubular condenser
C8	.05 MFD tubular condenser	C16	270 MMF mica condensers
C10	2 MFD 1000V condenser	C17&C18	5.-5. MFD filter condensers
C11	.05 MFD tubular condenser		

MISC. PARTS

CH1	10 henry 50 MA Choke	1	cabinet
	Power transformer	1	chassis
S1	SPDT toggle switch	1	panel
S2	SPDT toggle switch	9	knobs
S3	single pole 5 pos. rotary switch	1	pilot light
S4	SIST toggle switch	1	5BP1 tube
6	binding posts	2	6SJ7 tubes
4	insulating washers for binding posts	1	884 or 6Q5
5	octal sockets & rings	2	5Y3 tubes
1	CR tube socket & ring	1	coil hookup wire
1	CR socket bracket	1	handle & screws
1	CR tube panel flange	1	set screws & nuts
1	line cord	1	length spaghetti tubing
1	dual fuse mtg. & fuses	1	set blueprints & instructions
2	grommets	1	parts list
1	single terminal strip		

HEATH CO.
BENTON HARBOR, MICH.
1-27-48