

O-5 OSCILLOSCOPE PARTS LIST

Part No.	Parts Per Kit	Description	Part No.	Parts Per Kit	Description
Resistors			O38	2	1 Lug Terminal Strip
O124	1	10 Ohm	S32	2	2 Lug Terminal Strip
O14	1	470 Ohm	SW37	2	3 Lug Terminal Strip
SW12	4	1,000 Ohm	O114	2	4 Lug Terminal Strip
G12	2	5,600 Ohm	Pilot Light Assembly		
O11	1	10,000 Ohm	O40	1	Nut
FM36	1	27,000 Ohm	O41	1	Bushing
A10	1	47,000-51,000 Ohm	O42	1	Jewel
O12	2	100,000 Ohm	O52	1	Socket
K34	4	220,000 Ohm	Knobs--Terminals		
O18	1	470,000 Ohm	O51	9	Pointer Knobs
O17	1	1 Megohm	O48	6	Binding Posts
O10	7	3.3 Megohm	V77R	1	Red Banana Jack
G18	2	47,000-51,000 Ohm 1 W.	M28	1	Banana Jack Insert
O116	1	4,700-6,00 Ohm 2 W.	Nuts--Bolts--Washers		
O19	1	100,000 Ohm 2 W.	O31	36	6-32 x $\frac{3}{8}$ " screws
O113	1	470,000 Ohm 2 W.	G52	4	8-32 x $\frac{3}{8}$ " screws
Condensers			O30	2	10-24 x $\frac{3}{8}$ " Handle screws
O117	1	100 MMF Mica or Cer.	O102	4	#6 x $\frac{3}{8}$ " Sheet Metal screws
TS36	1	680 MMF Ceramic	S22	42	6-32 nuts
O118	5	6800 MMF (.0068 MFD)	TP16	4	8-32 nuts
O24	1	.01 MFD Paper Tub.	O33	9	Control nuts
O25	2	.02 MFD Paper Tub.	TS72	36	#6 lockwashers
O49	5	.1 MFD Paper Tub.	O101	9	Control Lockwashers
G23	4	.2-.25 MFD Paper Tub.	O28	9	Nickel washers
O115	1	.5 MFD Paper Tub.	O26	4	Fibre Shoulder washers
O119	1	1 MFD @ 1,000 V. Metal	O27	4	Fibre Flat washer
O96	1	20-20-20 MFD Elect.	O37	7	Solder lugs
Controls			O44	1	Speednut for Jack
O58	2	100,000 Ohm	Sheet Metal Parts		
O59	1	250,000 Ohm	O85B	1	Chassis
O56	2	1 Megohm	O86B	1	Panel
O112	1	.25 11 Megohm dual	O65L	1	Panel Bracket
S15	2	4 Megohm dual	O65R	1	Panel Bracket
Switches			O70	1	CR tube Bracket
O111	1	4P. 5 Pos. Rotary	O80A	1	CR tube Panel Ring
O94	1	SPST Slide	O106A	2	CR tube Shield Brackets
O95	1	SPDT Slide	O110	1	CR tube Shield
G59	1	DPDT Slide	O88	1	Cabinet
Tubes--Lamps			O79	1	Handle
O66	2	5Y3 GT tubes	Miscellaneous		
T38	4	6SH7 or 6SH7 GT tubes	O72	1	Power Transformer (S122)
G44	1	6SN7 GT tube	G40	1	Condenser Mtg. Wafer
O87	1	5BP1, 5BP4 or 5GP1 (CR tube)	O63	1	Fuse Block set
O39	1	#47 pilot lamp	O82	1	Grid Screen
Sockets--Terminal Strips			O34	4	Rubber Feet
O54	7	Octal Sockets	O35	1	$\frac{3}{8}$ " Grommet
O43	7	Socket Rings	O36	1	$\frac{1}{2}$ " Grommet
O55	1	CR tube Socket	O78	1	Line Cord
O47	1	CR Socket Ring	O77	1	Length Hookup Wire
			O81	1	Length Spaghetti